


| | | | | | | | | | |
|----------------------------------|-----------|-------|------|------|------|------|------|------|------|
| FREE TOLERANCES FOR MACHINING | RANGE | OVER | 0.5 | 3 | 6 | 30 | 120 | 315 | 1000 |
| | | TO | 3 | 6 | 30 | 120 | 315 | 1000 | 2000 |
| | TOLERANCE | ±0.15 | ±0.1 | ±0.2 | ±0.3 | ±0.5 | ±0.8 | ±1.2 | |

~ ALL OVER



NOTE:-

1. ROUND OFF SHARP EDGES

| | | | | | |
|-----------|--|---------------------|--------------------------|--------------|----------|
| 1 | REDUCTION GEAR BOX ASSLY, I=5.166 FOR BALL MILL | Fe410WA, IS:2062-92 | 5.92 | | 33 |
| QTY. | DESCRIPTION OF ASSY. | MATERIAL | UNIT WEIGHT | ASSY.DRG.No. | POS. NO. |
| W.D.No. : | | | ALL DIMENSIONS ARE IN mm | | |
| | | | REF.DRG.No. --- | | |

| | | | | | | |
|--------------|----------|---------------|------|---------|---------------|------|
| SCALE NTS | DRAWN | NAME | SIGN | DATE | | |
| | CHECKED | | | 14-1-19 | | |
| | APPROVED | | | | | |
| | | TITLE | | | DRG.No. | REV. |
| | | CASING | | | 085003/B-1113 | 0 |